



PHOTO 1: Looking north at asphalt entrance along western property boundary.



PHOTO 2: View looking southeast over property from west-boundary.



PHOTO 3: Looking south from west-central boundary of the site.



PHOTO 4: One of several utility drainage vaults noted at the site.



PHOTO 5: Sign and associated electrical panel and pad-mounted transformer in southeast corner of the site.



PHOTO 6: Close-up of electrical panel and pad-mounted transformer associated with large sign noted in photograph 5.



PHOTO 7: Looking east from southwest corner of site. Note low lying area and storm water pollution controls (seeding and straw).



PHOTO 8: Storm drain filtration unit cover noted near southeast corner of the site.



PHOTO 9: Gravel and concrete debris noted within southeast portion of the site.



PHOTO 10: Miscellaneous concrete debris and uneven ground in northeastern portion of site.



PHOTO 11: Utility vault boxes of electrical and water/sewer.



PHOTO 12: One of two concrete entrance driveways noted along the northern property boundary.



PHOTO 13: View looking southwest over the site from the northeast corner.



PHOTO 14: View of stubbed sanitary sewer casing along the site western boundary.



www.Kleinfelder.com

Proj. No: 123381.E01
Graphic By: G. GOMEZ
Graphic Date: 12/18/12
Checked By: D.H.
File Name:STO12D138.fh11

SITE PHOTOGRAPHS
1880 DANIELS STREET
APN 222-25-06
MANTECA, CALIFORNIA

Plate

3

Copyright Kleinfelder, 2011